

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L13	107	(bear\$3 and surface and rot at \$3 and (cut \$4 or machin\$3 or bor\$3) and (tool or appar at us or device or machine) and (discont inuit ies or grooves or indent at ions or bumps) and (shape or cont our)).clm.	US-PGPUB	OR	ON	2008/08/17 16:13
L14	130	(bear\$3 and surface and rot at \$3 and (cut \$4 or machin\$3 or bor\$3) and (tool or appar at us or device or machine) and (discont inuit ies or grooves or indent at ions or bumps) and (process or procedur e or met hod)).clm.	US-PGPUB	OR	ON	2008/08/17 16:15
L15	77	14 not 13	US-PGPUB	OR	ON	2008/08/17 16:15
L16	3	(bear\$3 and surface and rot at \$3 and (cut \$4 or machin\$3 or bor\$3) and (tool or appar at us or device or machine) and (discont inuit ies or grooves or indent at ions or bumps) and (polar or equat or)).clm.	US-PGPUB	OR	ON	2008/08/17 16:17

L17	0	(bear\$3 and surface and rot at \$3 and (cut \$4 or machine\$3 or bor\$3) and (tool or apparatus or device or machine) and (discontinuities or grooves or indentations or bumps) and non-cylindrical).clm.	US-PGPUB	OR	ON	2008/08/17 16:18
L18	0	(bear\$3 and (irregular near surface) and rot at \$3 and (cut \$4 or machine\$3 or bor\$3) and (tool or apparatus or device or machine) and (discontinuities or grooves or indentations or bumps) and non-cylindrical).clm.	US-PGPUB	OR	ON	2008/08/17 16:18
L19	0	(bear\$3 and irregular and surface and rot at \$3 and (cut \$4 or machine\$3 or bor\$3) and (tool or apparatus or device or machine) and (discontinuities or grooves or indentations or bumps) and (polar or equatorial)).clm.	US-PGPUB	OR	ON	2008/08/17 16:19

8/17/08 4:29:50 PM

C:\Documents and Settings\jcozart\My Documents\EAST\workspaces\SphericalSurface-Method.wsp